

BUILDING #1
(SIDE FACING THE PRAYER HALL WITH 3 ADJACENT DORMITORY ROOMS)

DEBOCHE NUNNERY, NEPAL
 PHOTO TIMELINE



2014 Building #1 Dormitory Rooms before earthquake



2015- Building #1- Dormitory rooms- Earthquake damage



2015- Building #1- Dormitory rooms- Earthquake damage



2016- Repairs to the Dormitory Rooms.
 New red metal siding.

BUILDING #1
(SIDE FACING ENTRY PATH INTO DEBOCHE- WITH 2 ADJACENT STRUCTURES)



2016- Building #1 Wall and roof damage from earthquake
 No visible repairs



2016- Building #1 Wall and roof damage from earthquake
 No visible repairs