

BUILDING #4-
Formerly ANI PEMA'S RESIDENCE
DEBOCHE NUNNERY, NEPAL
PHOTO TIMELINE



2014



2014



2014- Enclosed courtyard with window. Formerly used by Ani Pema to offer her blessings while in retreat.



2015- Enclosed courtyard with window. Collapsed from April 2015 earthquake.



2016 Post Earthquake- Reconstruction in process



2016 Post Earthquake - Reconstruction in process