

BUILDING #6- FORMER RESIDENCE

(Now serving as PRAYER ROOM)

DEBOCHE NUNNERY

PHOTO TIMELINE



2014- Building #6- Newly constructed nun's residence



2015- Building #6-Earthquake damage



2016- Tent vestibule installed to create vestibule for new Prayer Room (Red Cross Tent)



2016- Reconstructed Walls. Metal siding added under roof.



2016- Building #6 becomes new Prayer Room due to the damaged Prayer Hall



2016- Interior of tent vestibule/ entry door. Sandals in vestibule