

## KITCHEN BUILDING

DEBOCHE NUNNERY

PHOTO TIMELINE



**2014** Pre earthquake



**2016** Reconstruction in progress

New exterior door added- likely due to blocked entry access from damaged interior courtyard



**2016** (Kitchen building on right side)



**2016** (Kitchen building on left. Prayer Hall on right)



**2016** New exterior door location from inside kitchen



**2016** New exterior door