

## NUN'S RESIDENCES – Buildings #2 & #5

DEBOCHE NUNNERY

PHOTO TIMELINE



**2014-** Site View

Adjacent Nun Residences- in center of photo  
(#2 on left side, #5 on right side)



**2016-** Site View- Post earthquake reconstruction

Remaining residence #2 is expanded.  
Damaged residence #5 has been demolished.



**2014** - 2 Adjacent Nun Residences

(#2 on left, #5 on right)



**2016-** Post earthquake reconstruction

Remaining #2 residence is expanded.  
(Damaged residence #5 has been demolished)



**2014-** Nun Residence #2



**2016-** Post earthquake reconstruction

Nun Residence #2- expanded